

26-Jul-05

**South 7th Street & Pike Road
DEP on-site Needs Analysis Results (*)**

PSA- 13		
<i>Total Number of Properties</i>	23	
<i>Vacant</i>	2	
Category	Number	% (1)
Confirmed Malfunctions	10	47.62%
Suspected Malfunctions	2	9.52%
Potential Malfunctions	6	28.57%
No Malfunctions	3	14.29%
Total Surveyed	21	

(1) % of surveyed properties

* Results based upon data provided by Brian Miller
UMIT SEO